



**Figure 15a.** Borehole geophysical logs of test hole 1 (Sh:V-74) and hydrogeologic units of the shallow aquifer system southwest of the erosional scarp at Naval Support Activity Memphis, Millington, Tennessee.